

FEB 1 9 1982

# 

FOR COATINGS. RESINS AND RELATED MATERIALS

(Approved by U.S. Department of Labor "Essentially Similar" to Form QSHA-30)

DATE OF PREP

3/24/80

Section i

## oto Inc.

Administrative and Research Center

1700 SOUTH MT. PROSPECT ROAD, DES PLAINES, ILLINOIS 60018

EMERGENCY TELEPHONE 312-391-9000

PRODUCT CLASS

Epoxy Polyamide

Primer Activator

MANUFACTURERS CODE IDENTIFICATION

910 - 736

TRADE NAME

Section II — HAZARDOUS INGREDIENTS						
INGREDIENT	PERCENT	TU PPM mg/M <sup>a</sup>		LEL	VAPOR PRESQUAE	
					020°C, mm	
Isopropanol - Skin	55	400	980	2.0	32	
Toluene-Skin	25	100	375	1.2	35	
CONFIDENTIAL INFORMÁTION						
THIS INFORMATION IS CONFIDENTIAL AND IS THE PROPERTY OF DISOTO, INC. IT IS DISCLOSED ONLY FOR THE PURPOSES R. Q. III. D BY LAW. NO OTHER USE OR DISCLOSURE IS AUTHORIZED.						
			NA = No	Appli	able	

#### Section III - PHYSICAL DATA

BOILING RANGE

180-232°F.

82-111°C.

VAPOR DENSITY

X HEAVIER.

LIGHTER, THAN AIR

PERCENT VOLATILE 84. I

# Section IV - FIRE AND EXPLOSION HAZARD DATA

DOT CATEGORY

EXTINGUISHING MEDIA

Flammable Liquid

FLASH POINT

45°F. 7.2°C. (Closed cup)

LEL See II

OSHA-Flammable Liquid-Class 1B

Use National Fire Protection Association Class B extinguishers

(Carbon dioxide, dry chemical or foam)

UNUSUAL FIRE AND EXPLOSION HAZAROS Keep containers tightly closed. Isolate from heat, electrical equipment, sparks and open flame. Closed containers may explode when exposed to extreme heat. Do not apply to hot surfaces.

special Plas Fighting Procedures Water spray may be ineffective. Water may be used to cool closed containers to prevent pressure build-up and possible auto ignition or explosion when exposed to extreme heat. If water is used, fog nozzles are preferable.

Section V - HEATTH HAZARD DATA  THRESHOLD INTIVALUE See II (Not Established for Product)  ###################################	
Inhalation: Anesthetic. Irritation of the respiratory to a cute nervous system depression characterized by headache, dizziness, staggering gait, confusion, unconsciousness or coma. Others as noted in some system depression characterized by headache, dizziness, staggering gait, confusion, unconsciousness or coma. Others as noted in some system and confusion, unconsciousness or coma. Others as noted in some system as a confusion system of the syste	
Keep warm and quiet. Notify a physician. Skin Contact: Wash affected areas with water. Remove contaminated clothing. Consult a physician. Eye Contact: Flush with water for 15 minutes. Consult a physician.  Section VI — REACTIVITY DATA  STABILITY UNISTABLE STABLE CONDITIONS TO ANDID INCOMPATABILITY (Waterwells to avoid: MAZARDOUS DECOMPOSITION PRODUCTS  Products of combustion are hazardous.  MAZARDOUS POLYMERIZATION MAY OCCUR WILL NOT OCCUR CONDITIONS TO AVOID  Section VII — SPILL OR LEAK PROCEDURES  STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Remove all sources of ignition. Avoid breathing vapors. Ventilate area. Remove with inert absorbent and non-sparking tools.  WASTE DISPOSAL METHOD Dispose in accordance with local, State and federal regular Incinerate in approved facility. Do not incinerate closed containers.	
STABILITY UNISTABLE STABLE CONDITIONS TO AVOID INCOMPATABILITY (Materials to avoid)  HAZARDOUS DECOMPOSITION PRODUCTS  Products of combustion are hazardous.  HAZARDOUS POLYMERIZATION MAY OCCUR WILL NOT OCCUR CONDITIONS TO AVOID  Section VII — SPILL OR LEAK PROCEDURES  STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Remove all sources of ignition. Avoid breathing vapors. Ventilate area. Remove with inert absorbent and non-sparking tools.  WASTEDISPOSAL METHOD Dispose in accordance with local, Jtate and federal regular Incinerate in approved facility. Do not incinerate closed containers.	thing.
INCOMPATABILITY (Materials to avoid:  HAZARDOUS DECOMPOSITION PRODUCTS  Products of combustion are hazardous.  HAZARDOUS POLYMERIZATION MAY OCCUR WILL NOT OCCUR  CONDITIONS TO AVOID  Section VII — SPILL OR LEAK PROCEDURES  STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Remove all sources of ignition. Avoid breathing vapors. Ventilate area. Remove with inert absorbent and non- sparking tools.  WASTE DISPOSAL METHOD Dispose in accordance with local, State and federal regular Incinerate in approved facility. Do not incinerate closed containers.	
Products of combustion are hazardous.  HAZARDOUS POLYMERIZATION MAYOCCUR WILL NOT OCCUR CONDITIONS TO AVOID  Section VII — SPILL OR LEAK PROCEDURES  STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Remove all sources of ignition. Avoid breathing vapors. Ventilate area. Remove with inert absorbent and non-sparking tools.  WASTEDISPOSAL METHOD Dispose in accordance with local, state and federal regular Incinerate in approved facility. Do not incinerate closed containers.	
Section VII — SPILL OR LEAK PROCEDURES  STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Remove all sources of ignition. Avoid breathing vapors. Ventilate area. Remove with inert absorbent and non-sparking tools.  WASTE DISPOSAL METHOD Dispose in accordance with local, State and federal regular Incinerate in approved facility. Do not incinerate closed containers.	
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Remove all sources of ignition. Avoid breathing vapors. Ventilate area. Remove with inert absorbent and non-sparking tools.  WASTEDISPOSAL METHOD Dispose in accordance with local, state and federal regulations are the containers.	÷
breathing vapors. Ventilate area. Remove with inert absorbent and non-sparking tools.  waste DISPOSAL METHOD Dispose in accordance with local, state and federal regulations are in approved facility. Do not incinerate closed containers.	
Section VIII - SPECIAL PROTECTION INFORMATION	
AANIAH AH - AI WANNEL HA LWALLAND AND HAND	
RESPIRATORY PROTECTION In outdoor or open areas use NIOSH approved mechanical firespirator.  In restricted ventilation areas use NIOSH approved chemical-mechanical files of the confined areas use NIOSH approved chemical-mechanical files.	

### Section IX - SPECIAL PRECAUTIONS

EVERNOTECTION Use safety eyeware designed to protect against splash of liquids. OTHER PROTECTIVE EQUIPMENT Prevent prolonged skin contact with contaminated clothing.

VENTILATION Where employees may be exposed, provide general dilution or local exhaust ventilation in volume and pattern to keep TLV of hazardous ingredients

in Section II below recommended (ACGIH) or regulated (OSHA) limit. Where employees will not be exposed, keep LEL in Section II below 25% of limit. X Required

Recommended:

PROTECTIVE GLOVES

PRECAUTIONS TO BE TAKEN IN MANDLING AND STORING DO NOT STORE above 120°F. Store large quantitie in buildings designed and protected for storage of flammable liquids.

OTHER PRECAUTIONS DO NOT take internally. Containers should be grounded when pouring. Avoid free fall of liquid in excess of a few inches. Do not sand, flame cut, braze or weld without NIOSH approved respirator or appropriate ventilation. Observe container precautionary label warnings.

Prepared by: QD Rokes